

Donning and Doffing of Personal Protective Equipment

Donning

Identify the hazard level and required level of PPE. *For current Novel Coronavirus, mask, eye protection, face shield, gown and gloves.*

- 1 Perform hand hygiene



- 2 Put on a gown



- 3 Put on N95 mask, eyewear and face shield



- 4 Put on gloves (over the cuff of the gown)



Doffing

Doffing presents the greatest risk for cross contamination. *Perform hand hygiene every time you remove a piece of PPE.*

- 1 Tear off the gown and roll the gown and gloves together inside out to remove



- 2 Perform hand hygiene



- 3 Remove face shield away from your face. Perform hand hygiene.



- 4 Remove eyewear away from your face. Perform hand hygiene.



- 5 Remove N95 away from your face. Perform hand hygiene.

