Tom Mohan Drainage Superintendent Municipality of West Elgin 22413 Hoskins Line Rodney, Ontario NOL 2C0

Dear Mr. Mohan

Re:

Assessment Splits Zoller Drain (1999)

Severace File Number #E81-2023

Our Job No. 224170-1

S

SPRIET ASSOCIATES

ENGINEERS & ARCHITECTS 155 York Street London, Ontario N6A 1A8 Tel. (519) 672-4100 Fax (519) 433-9351 E-mail: mail@spriet.on.ca

maii: maii@spriet.on www.spriet.on.ca

In accordance with Section 65 of the Drainage Act we hereby make the following apportionment with respect to the severance on the above noted drain.

## 1. Zoller Drain (1999)

The lines in the Schedule of Assessment on page 6,15,26 for the above noted drain contained in the report dated January 11, 1999 by the Todgham & Case Associates Inc. which now reads:

Pt. 17 Pt. 19	9.14 8.20	60-079 (Vinchente Okollsan) 1-176-01 (Vinchente Okollsan)	\$	Outlet 36.00 32.00	\$	Total 36.00 32.00
						5.00
Pt. 17	0.11	1-175 (Previous Severed)		5.00		5.00
w read in si	x lines as	follows:		Outlet		Total
Pt. 19	6.74	1-176-01 (North of Hydro Easement)	\$	28.00	\$	28.00
Pt. 19	1.00	1-176-01 (South of Hydro Easement)		7.00		7.00
Pt. 17	0.47			5.00		5.00
Pt. 17	0.21			3.00		3.00
Pt. 17	0.46	60-079 (North of Hydro Easement)		5.00		5.00
Pt. 17	8.68	60-079 (South of Hydro Easement)		30.00		30.00
	Pt. 19 Pt. 17 Pt. 17  w read in si Pt. 19 Pt. 19 Pt. 17 Pt. 17 Pt. 17	Pt. 19 8.20 Pt. 17 0.11 Pt. 17 0.11  ow read in six lines as  Pt. 19 6.74 Pt. 19 1.00 Pt. 17 0.47 Pt. 17 0.21 Pt. 17 0.46	Pt. 19 8.20 1-176-01 (Vinchente Okollsan) Pt. 17 0.11 1-175-01 (Previous Severed) Pt. 17 0.11 1-175 (Previous Severed)  w read in six lines as follows:  Pt. 19 6.74 1-176-01 (North of Hydro Easement) Pt. 19 1.00 1-176-01 (South of Hydro Easement) Pt. 17 0.47 1-175-01 (Previous Severed) Pt. 17 0.21 1-175 (Previous Severed) Pt. 17 0.46 60-079 (North of Hydro Easement)	Pt. 19 8.20 1-176-01 (Vinchente Okollsan) Pt. 17 0.11 1-175-01 (Previous Severed) Pt. 17 0.11 1-175 (Previous Severed)  w read in six lines as follows:  Pt. 19 6.74 1-176-01 (North of Hydro Easement) Pt. 19 1.00 1-176-01 (South of Hydro Easement) Pt. 17 0.47 1-175-01 (Previous Severed) Pt. 17 0.21 1-175 (Previous Severed) Pt. 17 0.46 60-079 (North of Hydro Easement)	Pt. 17       9.14       60-079 (Vinchente Okollsan)       \$ 36.00         Pt. 19       8.20       1-176-01 (Vinchente Okollsan)       32.00         Pt. 17       0.11       1-175-01 (Previous Severed)       5.00         Pt. 17       0.11       1-175 (Previous Severed)       5.00         Pw read in six lines as follows:       Outlet         Pt. 19       6.74       1-176-01 (North of Hydro Easement)       \$ 28.00         Pt. 19       1.00       1-176-01 (South of Hydro Easement)       7.00         Pt. 17       0.47       1-175-01 (Previous Severed)       5.00         Pt. 17       0.21       1-175 (Previous Severed)       3.00         Pt. 17       0.46       60-079 (North of Hydro Easement)       5.00	Pt. 17       9.14       60-079 (Vinchente Okollsan)       \$ 36.00 \$         Pt. 19       8.20       1-176-01 (Vinchente Okollsan)       32.00         Pt. 17       0.11       1-175-01 (Previous Severed)       5.00         Pt. 17       0.11       1-175 (Previous Severed)       5.00         Pw read in six lines as follows:       Outlet         Pt. 19       6.74       1-176-01 (North of Hydro Easement)       \$ 28.00 \$         Pt. 19       1.00       1-176-01 (South of Hydro Easement)       7.00         Pt. 17       0.47       1-175-01 (Previous Severed)       5.00         Pt. 17       0.21       1-175 (Previous Severed)       3.00         Pt. 17       0.46       60-079 (North of Hydro Easement)       5.00

It is our pleasure to be of service.

Yours truly,

SPRIET ASSOCIATES LONDON LIMITED

B. Widner P.Eng